

9 MAR 5

Work Order ID 156363***156363***

Page 1

Friday, January 27, 2017 1:33:25 PM

Item ID: D412-711-021 **Accept** ***N900040100*** **Setup Start** ***NS1***
Revision ID: **Stop** ***NS2***
Item Name: Vertical Reference Door Modification LH
Start Date: 1/13/2017 **Start Qty:** 1.00 ***1*** **Cust Item ID:**
Required Date: 1/27/2017 **Req'd Qty:** 1.00 ***1*** **Customer:**
Reference:

Approvals: **Process Plan:** DAS 21 9-89 **Date:** FEB 01 2017 **Tooling:** SPC (Y/N): **Date:**
QC: **Run Start** ***NR1***
Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D412-711	K								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefiles and create labels per PPP D412-711-021 CHG002								
120	Pick Kit	0.00							
120	Purchasing								
Packaging	Memo	0.00							
Packaging									
130	QC4- 100% Inspect kits for completeness	0.00							
130									
QC	Memo	0.00							
Quality Control									

17-09-27

DAS
28
9-89

MAR 06 2017

FEB 28 2017

DAS
6
9-89DAS
27
9-89DAS
28
9-89

MAR 06 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER :							

Work Order ID 156363

Friday, January 27, 2017 1:33:25 PM

156363

Page 2

Item ID: D412-711-021

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 1/27/2017 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

150

0.00

150

Packaging

Memo

0.00

Identify and pack for shipping as per PPP D412-711-021

Location: _____

PPP rev: _____

DAS
28
9-89

MAR 06 2017

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.02

Quality Control

DAS
21
9-89

MAR 06 2017

DAS
21
9-89

MAR 06 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : _____					

Picklist Print

Friday, January 27, 2017 1:33:28 PM

Page 1

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A 11.04.07 new issue DD verf:EC
14.04.25 ECN14-548 DD verf:JLM

IPP Rev:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4324-011 *D4324-011* Armrest Assembly		Manufactured	No				Each	0.0000	1	1			
D412-761-043 *D412-761-043* Modified Latch Mechanism, LH		Manufactured	No			120	Each	2.0000	1	1			
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				FG020		2							
				144456		2							
D412-711-101 *D412-711-101* Replacement Vertical Reference Window		Manufactured	No			120	Each	1.0000	1	1			
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				FG099		1							
				153013		1							
D3802-1-120 *D3802-1-120* Window Seal - 120"		Manufactured	No			120	Each	0.0000	1	1			
D4165-1 *D4165-1* Doubler		Manufactured	No			120	Each	4.0000	1	1			
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST236		4							
				153518		4							

MAR 03 2017

FEB 28 2017

FEB 28 2017

FEB 28 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER :							
Misidentified ☐	Past Due ☐								

Picklist Print

Friday, January 27, 2017 1:33:28 PM

Page 2

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

D4165-3 Manufactured No 120 Each 1.0000

D4165-3

Inner Door Panel

DAS
28
9-89

Location

Loc Qty

Loc Code

st238

1

141941

1

D4165-5 Manufactured No 120 Each 4.0000

D4165-5

Aft Rib

DAS
28
9-89

Location

Loc Qty

Loc Code

ST236

4

153541

4

D4165-7 Manufactured No 120 Each 4.0000

D4165-7

Fwd Rib

DAS
28
9-89

Location

Loc Qty

Loc Code

ST236

4

116604

4

D4165-9 Manufactured No 120 Each 4.0000

D4165-9

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

4

153523

4

D4165-11 Manufactured No 120 Each 1.0000

D4165-11

Door Cover Panel

DAS
28
9-89

Location

Loc Qty

Loc Code

st238

1

141938

1

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

Friday, January 27, 2017 1:33:28 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Friday, January 27, 2017 1:33:28 PM

Page 3

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

D4207-1 Manufactured No 120 Each 1.0000

D4207-1

Window Retainer

DAS
28
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

1

141942

1

D4207-3 Manufactured No 120 Each 1.0000

D4207-3

Instrument Window

DAS
28
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

1

147147

1

D4269-1 Manufactured No 120 Each 5.0000

D4269-1

Angle

DAS
28
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST089

5

143364

5

D4269-3 Manufactured No 120 Each 1.0000

D4269-3

Angle

DAS
28
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST089

1

141939

1

D4269-5 Manufactured No 120 Each 2.0000

D4269-5

Angle

DAS
28
9-89

1 1

**

DAS
6
9-89

FEB 28 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST237

2

153604

2

Friday, January 27, 2017 1:33:29 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER :					

Picklist Print

Friday, January 27, 2017 1:33:29 PM

Page 4

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

D4269-7

Manufactured No

120 Each

2.0000

1 1

D4269-7

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

2

153605

2

D4327-1

Manufactured No

120 Each

1.0000

1 1

D4327-1

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

1

141940

1

D4327-3

Manufactured No

120 Each

1.0000

1 1

D4327-3

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

1

141943

1

D4385-1

Manufactured No

120 Each

3.0000

2 2

D4385-1

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST095

3

147080

3

6/13/2017

DAS
6
9-89

DAS
27
9-89

DAS
6
9-89

DAS
27
9-89

DAS
6
9-89

DAS
27
9-89

DAS
6
9-89

DAS
27
9-89

FEB 28 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval				
Description Work Order Deviation				Disposition				Completed By			
Root Cause				FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐		No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐		Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐		Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	
OTHER : _____											

Picklist Print

Friday, January 27, 2017 1:33:29 PM

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

AN3-3A
AN3-3A
Bolt

Purchased No

120 Each

195.0000

22 22

DAS
6
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

ST350

195

m136199

95

m136643

100

136741

AN3-4A
AN3-4A
Bolt

Purchased No

120 Each

418.0000

20 20

DAS
6
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

ST350

418

m135704

85

m136579

333

20

AN3-6A
AN3-6A
Bolt

Purchased No

120 Each

237.0000

26 26

DAS
6
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

over003

188

153844

188

ST350

49

M134955

49

20

AN3-12A
AN3-12A
Bolt

Purchased No

120 Each

350.0000

1 1

DAS
6
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

over003

206

153854

206

ST349

144

m135603

144

1

Friday, January 27, 2017 1:33:29 PM

Shop Packet Print

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER :							
Misidentified ☐	Past Due ☐								

Picklist Print

Friday, January 27, 2017 1:33:29 PM

Page 6

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

NAS1149F0332P

Purchased

No

120

Each

2,044.000

92

92

NAS1149F0332P

Washer

**

DAS
6
9-89

FEB 28 2017
DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

343

m133709

343

ST262

1701

m135948

5

m136442

1696

92

CR3242-4-2

Purchased

No

120

Each

117.0000

34

34

CR3242-4-2

RIVET

**

DAS
6
9-89

FEB 28 2017
DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST318

117

m134962

117

34

MS20426AD3-3

Purchased

No

120

Each

4,676.000

135

135

MS20426AD3-3

RIVET

**

DAS
6
9-89

FEB 28 2017
DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

fg108

400

M134946

200

M135354

120

M135894

80

GA

1606

M135274

1606

ST312

2670

M135274

2670

135

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Friday, January 27, 2017 1:33:29 PM

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

MS20426AD4-3

Purchased

No

120

Each

875.0000

140

140

MS20426AD4-3

Rivet

**

FEB 27 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

223

113064

223

ST312

652

m125807

652

120

Each

6,098.000

25

25

MS20470AD3-3

Purchased

No

MS20470AD3-3

RIVET, UNIVERSAL HEAD

**

FEB 27 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

803

1065

803

ST310

5295

16941

5295

120

Each

2,338.000

90

90

MS20470AD4-3

Purchased

No

MS20470AD4-3

Rivet, Universal Head

**

FEB 27 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

1073

2193

141

m135536

932

ST310

1265

m135536

1265

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Friday, January 27, 2017 1:33:29 PM

Page 8

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

120

Each

1,988.000

24

24

MS21042L3

Nut

**

Location

Loc Qty

Loc Code

FP001

100

m135945

100

GA

158

m134360

108

m135135

50

OVER007

1000

M136554

500

M136665

500

ST303

730

M136044

11

M136192

219

M136406

500

DAS
28
9-89

DAS
6
9-89
FEB 27 2017
DAS
27
9-89

MS21059L3

Purchased

No

120

Each

155.0000

4

4

MS21059L3

Nut Plate

**

Location

Loc Qty

Loc Code

GA

63

M136047

63

ST301

92

M135774

27

M136450

65

DAS
28
9-89

DAS
6
9-89
FEB 27 2017
DAS
27
9-89

MS21069L3

Purchased

No

120

Each

52.0000

34

34

MS21069L3

ANCHOR NUT

**

Location

Loc Qty

Loc Code

ST299

52

m135864

52

DAS
28
9-89

DAS
6
9-89
FEB 27 2017
DAS
27
9-89

Friday, January 27, 2017 1:33:29 PM

Shop Packet Print

Page 8

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Friday, January 27, 2017 1:33:29 PM

Page 9

Work Order ID: 156363

156363

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 1/13/2017

Required Date: 1/27/2017

Start Qty: 1.00

Required Qty: 1.00

MS21069L08

Purchased

No

120

Each

450.0000

8

8

MS21069L08

ANCHOR NUT

DAS
28
9-89

**

DAS
6
9-89

DAS
27
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

ST299

450

123522

450

MS21071L3

Purchased

No

120

Each

87.0000

3

3

MS21071L3

ANCHOR NUT

DAS
28
9-89

**

DAS
6
9-89

DAS
27
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

ST299

87

125654

87

MS21071L08

Purchased

No

120

Each

151.0000

1

1

MS21071L08

ANCHOR NUT

DAS
28
9-89

**

DAS
6
9-89

DAS
27
9-89

FEB 27 2017

Location

Loc Qty

Loc Code

ST299

151

102587

51

103447

100

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER :					

Work Order ID 156363

Friday, February 24, 2017 9:07:30 AM

156363

Page 2

Item ID: D412-711-021

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Vertical Reference Door Modification LH

Start Date: 3/1/2017 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 3/9/2017 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursTool ID Tool # Plan
Code Accept Reject Reject Insp.
Qty Qty Number Stamp

150

0.00

150

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D412-711-021

Location: _____

PPP rev: _____

DAS
21
9-89

FEB 27 2017

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.02

Quality Control

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	PART NUMBER	DESCRIPTION
					22	22	AN3-3A	BOLT
					20	20	AN3-4A	BOLT
					26	26	AN3-6A	BOLT
					1	1	AN3-12A	BOLT
					92	92	NAS1149F0332P	WASHER (OR AN960-10L)
					34	34	CR3242-4-2	RIVET
					135	135	MS20426AD3-3	RIVET
					140	140	MS20426AD4-3	RIVET
					25	25	MS20470AD3-3	RIVET
					90	90	MS20470AD4-3	RIVET
					24	24	MS21042L3	NUT
					4	4	MS21059L3	NUT PLATE
					34	34	MS21069L3	NUT PLATE
					8	8	MS21069L08	NUT PLATE
					3	3	MS21071L3	NUT PLATE
					1	1	MS21071L08	NUT PLATE
						1	204-030-853-125	LH COPILOT DOOR (204-030-853-137/-155)
1							D412-711-111	WIRING HARNESS, 212/412
B ₁							B ^D 4268-043	INSTRUMENT PANEL, 212/412 (REPLACES EA20469-15-412)
	1						D205-711-113	WIRING HARNESS, 205
	B ₁						B ^D 4268-041	INSTRUMENT PANEL, 205 (REPLACES EA20469-15-205)
		1					D204-711-115	WIRING HARNESS, 204
		B ₁					B ^E A20469-15-204	INSTRUMENT PANEL, 204
			1				D214-711-117	WIRING HARNESS, 214
			B ₁				B ^E A20469-15-214	INSTRUMENT PANEL, 214
				1			D212-711-119	WIRING HARNESS, EAGLE SINGLE
				B ₁			B ^D 4268-047	INSTRUMENT PANEL, EAGLE SINGLE

- (A) IF CUSTOMER PREFERS TO SUPPLY AND MODIFY THEIR OWN DOOR, D412-711-021 SHOULD BE SUPPLIED IN LIEU OF D412-711-041
(B) INSTRUMENT PANEL INCLUDED WITH HARNESS ABOVE

NOTES

1) WIRING HARNESSES:

For Bell 204/205/210 Wiring Harnesses, use drawing D2046904.
For Bell 212 Wiring Harnesses, use drawing D2046903*.
For Bell 214 Wiring Harnesses, use drawing D214-761-511.
For Bell 412 Wiring Harnesses, use drawing D412-711-901.
For Bell 212 modified per SH07-28/SR02831NY use D212-761-224
or D212-761-225 depending on aircraft s/n.

* Despite the note on the drawing, D2046903 is applicable to all 212 aircraft serial numbers

Wiring Harnesses will vary depending on aircraft s/n.

2) D412-711-101 REPLACEMENT WINDOW:

To increase downward viewing clarity, it is acceptable to cut a small section from the replacement window on its downward side per Figure 1 of this document. The cutout can be a maximum of 9.00" wide x 17.00" long (229mm x 432mm), measured along the profile of the replacement window. The corners of the cutout must have a minimum radius of 2" (50mm). The cutout should be located at least 1.0" (25mm) from the flange. The actual shape of the cutout can vary as desired, as long as the overall dimensions are within the specified limits. See Figure 1 for reference.

3) D412-711-043 SNAP VENT KIT:

It is acceptable to install a total of up to 2X D3932-1 Snap Vents (available from Dart) onto the D412-711-101 Replacement Window to provide ventilation into the cabin. Refer to Figure 1 for acceptable locations and size of cutouts.

4) It is acceptable to use MS21042L3 nuts to install the window in lieu of anchor nuts shown on D2046901.

APPROVED

DESIGN	RF	DART AEROSPACE LTD	
DRAWN	MB	HAWKESBURY, ONTARIO, CANADA	
CHECKED	ML	DRAWING NO.	REV. L
MFG. APPR.	N/A	D412-711	SHEET 3 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR NTS	
DATE	17.01.20	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

REFERENCE ONLY

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X								D412-711-011	VERTICAL REFERENCE DOOR INSTALLATION, 212/412
	X							D205-711-013	VERTICAL REFERENCE DOOR INSTALLATION, 205/210
		X						D204-711-015	VERTICAL REFERENCE DOOR INSTALLATION, 204
			X					D214-711-017	VERTICAL REFERENCE DOOR INSTALLATION, 214
				X				D212-711-019	VERTICAL REFERENCE DOOR EAGLE SINGLE
					X			D412-711-021	VERTICAL REFERENCE DOOR KIT
A ₁	A ₁	A ₁	A ₁	A ₁		X		D412-711-041	VERTICAL REFERENCE DOOR ASSEMBLY
							X	D412-711-043	SNAP VENT KIT
					1	1		D412-761-043	MODIFIED LATCH MECHANISM KIT, LH (REPLACES EA20469-23/-24/-25)
					1	1		D412-711-101	REPLACEMENT WINDOW (REPLACES EAGLE P/N EB212-100L / EA20469-3)
					1	1		D3802-1-120	RUBBER STRIP
							2	D3932-1	SNAP VENT
					1	1		D4165-1	DOUBLER
					1	1		D4165-3	DOOR INNER SKIN (REPLACES EA20469-18)
					1	1		* D4165-5	AFT RIB (REPLACES EA20469-34)
					1	1		** D4165-7	FWD RIB (REPLACES EA20469-31)
					1	1		D4165-9	ANGLE (REPLACES EA20469-17)
					1	1		D4165-11	DOOR COVER PANEL (REPLACES EA20469-21)
					1	1		D4207-1	WINDOW RETAINER (REPLACES EA20469 -14)
					1	1		D4207-3	WINDOW (REPLACES EA20469-13)
					1	1		* D4269-1	ANGLE (REPLACES EA20469-33)
					1	1		** D4269-3	ANGLE (REPLACES EA20469-30)
					1	1		** D4269-5	ANGLE (REPLACES EA20469-29)
					1	1		* D4269-7	ANGLE (REPLACES EA20469-32)
					1	1		D4324-011	ARM REST ASSEMBLY (REPLACES EA20469-16)
					1	1		D4327-1	ANGLE (REPLACES EA20469-11)
					1	1		D4327-3	ANGLE (REPLACES EA20469-07)
					2	2		D4385-1	PLACARD

* PART OF EA20469-10 REAR RIB ASSEMBLY
 ** PART OF EA20469-12 FWD RIB ASSEMBLY

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	MB		
CHECKED	ML	DRAWING NO. D412-711	REV. L
MFG. APPR.	N/A		SHEET 2 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS <i>[Signature]</i>	VERTICAL REFERENCE DOOR	NTS
DATE	17.01.20	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	